

## TABLES OF CONTENTS

	<b>Page</b>
Acknowledgements	iii
Abstract	iv
บทคัดย่อ	vi
List of Tables	x
List of Illustrations	xi
Chapter 1 Introduction	1
Chapter 2 Literature Review	3
Chapter 3 Experimental Procedure	12
3.1 Gas Flow Rate	12
3.2 Specimen Preparation	14
3.3 Nitridation and Carburization by Direct Metal-Gas Reaction	15
3.4 Nitridation by Direct Metal-Gas Reaction	19
3.5 Carburization by Directly Applying Voltages	20
3.6 Rutherford Backscattering Spectrometer	22
3.7 X-Ray Diffractometer	22
3.8 Energy Dispersive X-ray and Scanning Electron Microscopy	23
3.9 Microhardness Test	24
3.10 Wear Test	24
Chapter 4 Results and Discussion	26
4.1 Gas Flow Rate	26
4.2 Rutherford Backscattering Spectrometer	27
4.3 Film Thickness, Mass Increase and Density Increase	30
4.4 X-Ray Diffractometer	36
4.5 Energy Dispersive Spectroscopy	45

	<b>Page</b>
4.6 Scanning Electron Microscopy	53
4.7 Microhardness Test	69
4.8 Wear Test	72
Chapter 5 Conclusions and Suggestions	75
5.1 Conclusions	75
5.2 Suggestions	76
References	78
Appendix A Basic Backscattering Spectrometry for Thin Film	84
Appendix B XRD Reference Pattern	87
Curriculum Vitae	95

ลิขสิทธิ์มหาวิทยาลัยเชียงใหม่  
Copyright © by Chiang Mai University  
All rights reserved

## LIST OF TABLES

Table	Page
3.1 Chemical composition of MJ12 and MJ47 alloys.	14
4.1 The equations, calculated $\Delta H$ and $r^2$ for $\text{NH}_3$ , Ar and $\text{C}_2\text{H}_2$ .	27
4.2 Arrhenius type equation and calculated $Q$ for MJ12 and MJ47.	35
4.3 The penetration depth, mass increase and density increase for MJ12 and MJ47 by directly applying voltages.	36
4.4 Collection of the phases formed on MJ12 and MJ47 during nitridation and carburization.	39
4.5 Collection of the phases possibly formed on MJ12 and MJ47 during nitridation and carburization.	39
4.6 Collection of the phases formed on MJ12 and MJ47 during nitridation	43
4.7 Collection of the phases possibly formed on MJ12 and MJ47 during nitridation.	43
4.6 Wear rates of the alloys without and with nitridation and carburization at high temperature.	73
A.1 XRD reference pattern of the phases in these studies.	87
A.2 JCPDS number of the phases formed and possibly formed on MJ12 and MJ47 during nitridation and carburization.	91
A.3 JCPDS number of the phases formed and possibly formed on MJ12 and MJ47 during nitridation.	93
A.4 JCPDS number of the phases formed and possibly formed on MJ12 and MJ47 during carburization.	94

## LIST OF ILLUSTRATIONS

Figure	Page
2.1 Ti-Al phase diagram.	6
3.1 Gas flow rate measurement.	12
3.2 High temperature reaction chamber.	16
3.3 The disk with holder.	18
3.4 Carburization by directly applying voltages.	21
3.5 Wear track width.	25
4.1 Log $F$ versus log $\Delta H$ of $\text{NH}_3$ , Ar and $\text{C}_2\text{H}_2$ .	26
4.2 RBS spectra of (a) MJ12 and (b) MJ47 before and after nitridation by direct metal-gas reaction.	28
4.3 RBS spectra of (a) MJ12 and (b) MJ47 before and after carburization by directly applying voltages.	29
4.4 (a) Nitridation depth, (b) mass increase and (c) density increase of MJ12 and MJ47 with 1000–1300 K nitridation.	32
4.5 N atom in FCC structure of TiAl alloy.	34
4.6 Diffusion coefficient for MJ12 and MJ47 with 1000–1300 K nitridation.	34
4.7 XRD spectra of (a) MJ12 and (b) MJ47 with 1000–1300 K nitridation in $10.0 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and carburization in $0.05 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	37
4.8 XRD spectra of (a) MJ12 and (b) MJ47 with 1000–1300 K nitridation.	41
4.9 XRD spectra of (a) MJ12 and (b) MJ47 before and after carburization.	44
4.10 EDX spectra of (a) MJ12 and (b) MJ47 without and with 1000-1300 K nitridation and carburization in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and $0.01 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	47
4.11 EDX spectra of (a) MJ12 and (b) MJ47 without and with 1000-1300 K nitridation and carburization in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and $0.03 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	48
4.12 EDX spectra of (a) MJ12 and (b) MJ47 without and with 1000-1300 K nitridation and carburization in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and $0.05 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	49

<b>Figure</b>	<b>Page</b>
4.13 EDX spectra of (a) MJ12 and (b) MJ47 without and with 1000-1300 K nitridation.	50
4.14 EDX spectra of (a) MJ12 and (b) MJ47 before and after carburization.	52
4.15 SEM micrographs of the as-received (a) MJ12 and (b) MJ47.	54
4.16 SEM micrographs of MJ12 with (a) 1000 K (b) 1100 K (c) 1200 K and (d) 1300 K nitridation in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and carburization in $0.01 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	55
4.17 SEM micrographs of MJ47 with (a) 1000 K (b) 1100 K (c) 1200 K and (d) 1300 K nitridation in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and carburization in $0.01 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	57
4.18 SEM micrographs of MJ12 with (a) 1000 K (b) 1100 K (c) 1200 K and (d) 1300 K nitridation in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and carburization in $0.05 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	59
4.19 SEM micrographs of MJ47 with (a) 1000 K (b) 1100 K (c) 1200 K and (d) 1300 K nitridation in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and carburization in $0.05 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	61
4.20 SEM micrographs of MJ12 with (a) 1000 K (b) 1100 K (c) 1200 K and (d) 1300 K nitridation in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ .	64
4.21 SEM micrographs of MJ47 with (a) 1000 K (b) 1100 K (c) 1200 K and (d) 1300 K nitridation in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ .	66
4.22 SEM micrographs of (a) MJ12 and (b) MJ47 after carburization by directly applying voltages.	68
4.23 Knoop hardness of (a) MJ12 and (b) MJ47 nitrided in $10 \text{ cm}^3 \cdot \text{s}^{-1} \text{ NH}_3$ and carburized in 0.01, 0.03 and $0.05 \text{ cm}^3 \cdot \text{s}^{-1} \text{ C}_2\text{H}_2$ .	70
4.24 The Knoop hardness of MJ12 and MJ47 with 1000-1300 K nitridation.	71
4.25 The wear rates of MJ12 and MJ47 with 1000-1300 K nitridation.	74
A.1 Basic backscattering spectrometry for thin film.	86